United States of America

Department of Transportation -- Federal Abiation Administration

Supplemental Type Certificate

Number ST02073CH

This certificate issued to

West Star Aviation 796 Heritage Way Grand Junction, CO 81506

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

(See Type Certificate Data Sheet A16WE for complete certification basis)

Original Product - Type Certificate Number:

A16WE

Make:

Boeing

Model .

737-700, 737-800, 737-900

Description of Type Design Change:

Installation of a dual Rockwell Collins Enhanced Mode S Transponders in accordance with Haycock & Associates LLC Master Data List B737-3453-3754-01, Rev. B, dated November 13, 2004 or later FAA approved revision.

Limitations and Conditions:

1. Compatibility of this design change with previously approved modifications must be determined by the installer.

2. FAA Approved Flight Manual Supplement, Haycock & Associates LLC Document B737-3453-3754-100, Revision '-', dated November 19, 2004 or later FAA approved revision is a required part of this STC.

3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 20, 2004

Date of issuance: November 19, 2004

Date reissued: September 19, 2006; September 25, 2006

Date amended:

By direction of the Administrator

(Signature)

Charles L. Smalley, Manager Systems and Flight Test Branch

(Title)

Chicago Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.